

Observations made between 9 - 13 UT. After the observations it was found that the 100 MHz reference signal to the receiver was not connected correctly. No good data recorded, so no need to transfer or correlate.

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbaapr2011/v255nshlog>

Last update: **2015/12/18 16:38**

