

The field system was unable to control the antenna, so I manually steered the antenna at the right source and the field system was only controlling the Mark 5. The data seemed to get recorded, but ignore any field system off-source flags; the antenna was on source the entire time.

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbafeb2017/rk16mccdlog>

Last update: **2017/02/27 00:03**

