

Recording disk BI\_1 CURTV007A

Frequency modes did not change as expected. Therefore, delay cal was observed only at single freq. ICRF run stayed at single freq. until ~ 02:48 UT at which time I changed it manually.

03:35 - 03:39 UT: Stopped for maintenance.

Hobart has been alarming on-and-off for quite some time now, with the 'sun microsystem' button flashing. As far as I can tell, this is a benign error.

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajun2013/v255sholog>

Last update: **2015/12/18 16:38**

