

Onsource at approx 10:10 UTC

IF#1 Rcp has really bad sampler stats and very low sensitivity. Probabl't a hardware problem, but no one onsite to do a hardware reset.

Autophase cal at 13:23 seemed to fail. Rephased on M87 at 13:38:55 as the phase errors from Virgo structure were thiught to be smaller that the current phase errors.

rephased on calibrator at 13:51:03

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamay2017/gs039atlog>

Last update: **2017/05/27 00:03**

