

DAS Profile: VSOP.PRO

Dual RCP

SML @ 809 MHz

SMY @ 777 MHz

“recording started at 1427 “restarted @ 142830 with proper channels. “moved from da”moved to CURT V001B

“CURT V001B is not working... “recorded to /data/internal up until 154940 “switching to UTAS V002A then .

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbaoct2010/v252tholog>

Last update: **2015/12/18 16:38**

