

Sensitivity is low, probably due to the receiver being offset from some recent works in the focus cabin. Stability is unknown, PLL might have some locking issues.

From:

<https://www.atnf.csiro.au/people/Tasso.Tzioumis/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/Tasso.Tzioumis/vlbi/dokuwiki/doku.php/lbaops/lbaapr2021/v456fholog>

Last update: **2021/04/12 10:21**

