

recorded to ATNF-V012

DAS levels too high 20.00:00 UT

added attenuation

receiver cryo warming may be responsible. may have to interrupt schedule to vacuum receiver

From:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/doku.php/lbaops/lbajan2017/v329fholog> 

Last update: **2017/01/20 11:40**