

Tied antennas 12345.

It is likely that half the channels will not work from atca. Incorrect wiring to DAS, only discovered the next day.

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2009/rg001catlog>

Last update: **2015/12/18 16:38**

