

DSS34 (34m) is observing

Recorded to ATNF V011/B1-7 and some to an eSATA drive

2nd LO: IF1 501 MHz, IF2 501 MHz, RCP only, DCC5 SNT logging

DAS profile 64MHz_f.pro

(NOTE added on 10/08/31.. this profile gets

"64MHz_Spec_Flipped 0 0". The correlator may have to flipped the spectrum.)

DOY 209

Recorder problem at start

13:54:45 started recording

It has been raining.

16:41:00 end of schedule

Note added on 2010 August 20

A tsys file vx016bdss34.tsys has been uploaded to /pub/people/vlbi/incoming area.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2010/vx016btilog>



Last update: **2015/12/18 16:38**