

DAS profile 64MHz\_f.pro at start

changed to 64MHz\_n.pro at 03:28

DSS34 1st track: DCC06 (RCP)

DSS34 2nd track: DCC04 (RCP)

DSS35: DCC02 (RCP), DCC06 (LCP)

DOY 196

02:10 Recording with DSS-34 for 64MHz RCP

03:28:00 change DAS profile to 64MHz\_n.pro

03:32:45 fringes to Hobart good

03:58:15 on point for 1st source of the main schedule

04:22:05 found bug in predicts and corrected, has been on wrong point (1st source!)

04:46:50 stop and stow DSS-34

05:22:35 DSS-35 on point, dual pol recording

07:59:50 DSS-35 finished

08:00:00 DSS-34 RCP (DCC04) only recording starts

10:10:10 DSS-34 finished

Tsys log has been sent off

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2015/v447btdlog>

Last update: **2015/12/18 16:38**

