

Ak32 switched to recorder at 07:38 UT.

Had to attenuate inputs (-v 18) and all seems to be working ok.

LO reset to correct freq 07:53 UT.

Occasional Az errors and stops changing sources! Last 08:54 - 09:05 UT

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajun2014/v486daklog>

Last update: **2015/12/18 16:38**

