

DOY 167

X-band RCP/LCP

vsop\_f.pro

2ndLO freq. 448 MHz

02:41 DSS-36 started

02:59 Fringes to AT and Parkes detected

03:08 Fringe to AT, Mp, Pa detected

03:16 Due to connection engine hardware problem, antenna link has been disrupted, no antenna log record can be seen until 04:04

03:58 Ambient load has been accidentally set

04:15 Accidental recorder stop

05:00 Clear ambient load

05:25:16 Recorder restarted

09:10:14 Stop to stow antenna

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajun2017/v252bitilog?rev=1498002478>

Last update: **2017/06/21 09:47**

