

Mopra mm receiver package problems, 22 GHz receiver essentially warm at the start of the observations, so significantly reduced sensitivity

From:  
<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:  
<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajun2017/v492cmplog>

Last update: **2017/06/15 22:07**

