

Agilent : 16.6 GHz

SMLs 716.0 MHz

DAS profile : 16\_UL\_F.PRO

Data being recorded to ATNF V015B

Hobart has a problem with LCP, data being recorded, but we are getting RCP fringes only. Tests earlier determined that the problem is in the receiver itself.

From:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/doku.php/lbaops/lbamar2017/gg081cholog> 

Last update: **2017/03/08 09:10**