

Agilent : 16.6 GHz SMLs 716.0 MHz DAS profile : 16\_UL\_F.PRO Data being recorded to ATNF V015B Hobart has a problem with LCP, data being recorded, but we are getting RCP fringes only. Tests earlier determined that the problem is in the receiver itself.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2017/gg081cholog?rev=1488924619> 

Last update: **2017/03/08 09:10**