

Agilent : 16.6 GHz

SMLs 636.0 MHz

DAS profile : VSOP_HO.PRO

Data being recorded to ATNF V015B

Hobart has a problem with LCP, data being recorded, but we are getting RCP fringes only. Tests earlier determined that the problem is in the receiver itself.

changed equip.ctl file to reflect MKIV rack at 01:00 UT and restarted field system, now have sensible clock offsets restarted recording at 01:02:30 UT (67)

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2017/v252bfholog>

Last update: **2017/03/08 12:06**

