

<NOTE: Due to error with the VSIC board the recording stopped and restarted every second. Perhaps no valid data has been recorded?>

DAS profile: vsop_f.pro

First LO: 22.0 GHz

Send LO: 387 MHz

K2-WBDC mode: U/L, Circular

2017 DOY 068

11:05:37 On source 0537-441

13:51:22 Recorder stopped by accident.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2017/v544btilog>

Last update: **2017/03/10 09:05**

