

Hobart recording to ATNFV009A1-7.

only ~last minute of LCP 6.7/6.7 setup is useful, due to extremely poor das levels. (~22:16-22:17)

appears to be a problem with the receiver at 6.3 GHz...coherence cannot be achieved all the time...was not achieved during the fringe check, but was when main experiment started. tone was inserted briefly after setup change to check for coherence.

Tsys measurements for last 4 hours of experiemnt were wrong

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbanov2008/v255cholog>

Last update: **2015/12/18 16:38**

