

After redrudging the schedule, the systemp command was not re-included into the proc file. No systemp measurements until the problem was detected at 0515

DAS profile VSOP.PRO

Agilent - 13.04 GHz

2nd LOs set to 428, 684 MHz

Recorded data to disks V001B

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbanov2008/v271bcdlog>

Last update: **2015/12/18 16:38**

