

Refant W104

Started using DAS1 - started getting clock errors around 05:30 UTC. Swapped to DAS2 (same freq) at 06:00 UTC. May introduce delay jump in data.

All five antennas tied together.

Couldn't find fringes with hybrid mode so reverted to standard vlbi mode cfb64_vlbi during fringe check run before mnain expt started.

12:21 UT did a pcal at end of scan 25.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbanov2012/v471catlog>

Last update: **2015/12/18 16:38**

