

Recording to CURT V002B.

22 GHz pols are swapped A↔B on the receiver, unswapped at DAS.

LO setup file 2010Oct_13MMa.cmd required tweaking, current attens are:

C12 0 1

C40 8 4 8 8

~21:40UT. Tsys recording fixed by JER. Prior to this Tsys values are wrong.

From:

<https://www.atnf.csiro.au/people/Tasso.Tzioumis/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/Tasso.Tzioumis/vlbi/dokuwiki/doku.php/lbaops/lbaoct2010/v252upalog>

Last update: **2015/12/18 16:38**

