

DAS profile vsop_f.pro

DOY 293

17:11:57 Tid70m on point, recoding Ch1-2 (RCP) only and wrong freq. set by mistake (445MHz as per 485 MHz required)

17:14:20 Fringe test showed no fringes for Tid

17:29:40 Fringe confirmed but only for LCP

17:36:00 RCP frequency corrected

17:40:10 confirmed fringes with Tid70m at both RCP and LCP

17:36:53 DSS-35 started, recording data to DVP until 20:55

18:46:03 Tid70m finished, IF inputs for LBA-DR switched over to DSS-35 RCP/LCP.

20:55:35 DSS-35 finished observation

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbaoct2016/v454btilog>

Last update: **2016/10/20 09:51**

