

After 14:00 DAS started beeping. The second DAS IF1 is too low power level

14:21 Set Coarse ATTEN from 1 to 0 fot DAS2-IF1, stopped beeping

15:26 Tsys 35 37 35 38, az el 182 41

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbasep2015/v463gmplog>

Last update: **2015/12/18 16:38**

