

Hobart late starting experiment. Fault with telescope safety system means that antenna cannot operate.

Very little data collected for this experiment with Hobart. The antenna fault was fixed at around 01:30 UT, however, the wind then came up and the antenna was windstowed for most of the rest of the experiment.

From:

<https://www.atnf.csiro.au/people/Tasso.Tzioumis/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/Tasso.Tzioumis/vlbi/dokuwiki/doku.php/lbaops/lbasep2015/v527cholog>

Last update: **2015/12/18 16:38**

