

Agilent 16.6 GHz

SML01 636 MHz

DAS profile VSOP\_HO.PRO

No coherence seen with tone of 892.2 MHz - likely issue with tone port/vertex radiator.

Recording to Flexbuf disk0.

Fringes found in both polarisations.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbasep2015/vt02aaholog>

Last update: **2015/12/18 16:38**

