

DVP was used for this support.

Disk pack HOB+0064 was used and shipped to U-TAS

Note: It appears the DVP IF switch had an error at the time. The X-band RCP IF was mixed up with DSS-36 (other BWG antenna) S-band IF, expecting degraded sensitivity between 8290 MHz and 8410 MHz, especially from 01:35 to 04:10 UT when DSS-36 was tracking at X-band (i.e. DSS-36 S-band was almost in ambient load). Hopefully all the recorded channels from 8409 MHz to 8473 MHz are with minor impact.

DOY 267

00:18:04 on source MAXIJ1535

04:35:48 stop

04:36:04 stow antenna

From:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/doku.php/lbaops/lbasep2017/v456btilog>

Last update: **2017/10/12 09:49**

