

DVP recording

Note: Due to wrong frequency set up LCP was not recorded properly most of time except the last 35 minutes.

DOY 251

18:03:00 DSS-36 On source 1057-797, recording to PKS+0011

20:55:30 DSS-43 on source 2M-77

DOY 252

00:10 Disk swap over to JPL-0061

02:20:00 Frequency set up for LCP corrected. Perhaps no ChB signal until this for DSS-36 and DSS-43.

02:55:34 DSS-43 stop

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbasep2018/v329htilog>

Last update: **2018/09/13 11:30**

