

XRCP only. Pol confirmed with fringecheck

dbbc04 frequency incorrectly set to 468.00 MHz until 0310. Correct thereafter

DBBC

load=v271k.txt

dbbcifa=1,agc,1

dbbcifb=4,agc,1

dbbcform=astro

formatter set to mk5=ext:0x0000ffff:1:2 (correctly drugged)

Recording to HOB+1004

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbaapr2012/v271kyglog?rev=1335583057>

Last update: **2015/12/18 16:38**

