

Setup notes

Tied array 1245 1245.

Refant CA02.

abph -90 90!! to get cross pols right!

rms servo to tats 14 (to account for 0dB atten on 4dd)

gtp servo to 200 during setup.

tied array: ant 1245; gain 0.1; pol c

Delay glitch 04:30-04:37UT

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbadec2009/v289m12atlog>

Last update: **2015/12/18 16:38**

