

recording to ATNF v009a

Agilent @ 12.2 GHz

VSOP.PRO

SMY01 = 810 MHz (LO1) SMX01 = 810 MHz (LO2)

Had an odd problem with the Agilent at the start of experiment. The bandpass had power but there were no coherence tones visible. Fixed by re-issuing the Agilent 12 ghz command in oscillator control gui

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2010/vc117aholog>

Last update: **2015/12/18 16:38**

