

- Antenna was not refocussed from C-band (+20mm). Should be -23mm. May result in some small loss of sensitivity.
- RFI present in 64 MHz band. 2nd freq recorded and 1st freq set at 32 MHz to avoid the RFI. Use the 1st 2 columns of Tsys for ANTAB calibration.

(AKT - 15/3/06)

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2006/v193amplog>

Last update: **2015/12/18 16:38**

