

vt02f9 Setup:

Antennas	Pa-At-Mp-Ho-Cd
Start	74 06:00:00
Stop	74 06:55:00
PI	LBA fringe-check
Channel 1	8417 - 8433 MHz USB RCP
Channel 2	8417 - 8433 MHz USB LCP
Bandwidth	16 MHz
Recorder	Disk through S2
DAS Mode	at16s.pro
S2 Mode	32a4-2
Buggary Cable	out

Ftp: <ftp://ftp.atnf.csiro.au/pub/people/vlbi/vt02/vt02f9>

Comments:

Fringe check for v131bc

Buggary cable *not* installed

Record on /data/internal

Use RecordMode "Channel 1,3" in disko or (-c oxox in vsib_record)

On S2 type "uic feedthru on" if not already enabled

From: <http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link: <http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2006/vt02f9>

Last update: **2015/12/18 16:38**

