

Fringe check problem in preceeding expt, vc108ho. Ceduna off source throughout vc108.

Recording Hobart data on Mk5 pack USN-0193/2000/1024. Hobart started recording at UT 14:00.

Fine weather at both stations.

Changed disk packs to pks-0008 during afternoon. This module has no sticky labels

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2010/v271eholog>



Last update: **2015/12/18 16:38**