

No fringes to Ceduna during pre-experiment checks. However, we think that the system was working properly and the issue may have been with the mixed-modes between the LBA antennas involved in the fringe check. System was coherent, no issues with Mark 5 time, setup and injected tones appeared in the expected locations in the recorded data.

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2018/gg084acdlog>

Last update: **2018/03/14 07:42**

