

XRAID chassis faults

9/2/09 - **Xraid05** could not connect properly to the xserve admin tools, even with a software reset. Hard reboot required. *New IP required - tools and wiki page updated accordingly.??*

6/2/09 - **Xraid04** shut down incorrectly when powered down - left hand side partly shut down, right hand side remained operational (according to lights). Power cables had to be physically removed and replaced and the entire chassis effectively reset to resolve the problem. xraid admin tools are reconfigured for the new IP and no damage seems to have been done either to the chassis or to the disks which were in it.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/correlator/faults?rev=1234159533> 

Last update: **2009/02/09 17:05**