

Recording with REVERSED polarisations to work around a broken SMA connector.

Schedule worked fine as drudged.

Recording to HOB+1002

Problems with DBBC IF power reading masked the XLCP problem until after restarting the DBBC server.

Using

dbbcifa=2,agc,1 dbbcifb=4,agc,1

to handle the reversed pols.

Experiment halted at ~1800

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbaapr2014/v486ckelog>

Last update: **2015/12/18 16:38**

