

No fringes due to a hardware setup problem. The telescope oscillator had an unknown offset in frequency that caused the recorded signal to be corrupted. Offset amount or effect unknown.

From:
<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:
<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbaapr2021/v456gcdlog>

Last update: **2021/05/01 16:15**

