

DSS45 RCP Maser LOW-NOISE

(NOTE added on 10/08/31.. the DAS profile used 64MHz_f.pro gets

"64MHz_Spec_Flipped 0 0". The correlator may have to flipped the spectrum.)

09:15 started

10:10 finished

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbaaug2010/vt15rtilog>

Last update: **2015/12/18 16:38**

