

Lo's 777 and 809 MHz

RCP only

DAS profile VSOP.PRO

recording 4 channels 16MHz bandwidth

Coherence obtained, fringes seen

Began recording to HO disk set

Problems with remote backend developed at ~2300. Fixed by removing it and back to normal ~0050

Stowed due to strong wind 0212-0324.

Stowed due to strong wind 0415-0510, with a brief restart about 0435.

Recorder stopped at 04:44:38 with message "The recorder has stopped as scheduled". Restarted manually at 04:47:44.

Stowed due to strong wind 0537-0916, with a brief restart about 0835.

Stowed due to strong wind 0952-???.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbaaug2013/v252alholog>



Last update: **2015/12/18 16:38**