

Agilent : 11.1 GHz

SML01 and SML02 set to 468/810 MHz for ICRF mode and 810/810 MHz for masers

DAS Profile : VSOP.PRO

BG3 cable out

Data recorded to ATNFV008B

Observer : Simon

Comments : DAS samplers running hot due to failed fans. System seems to be working OK though. DAS IFP#1 levels near bottom of range for maser mode and slightly out of range at the top for the ICRF mode. Stats and tsys measurements OK for both though.

Power glitch at about 20:35 UT, antenna offsource required reboot of pcfsd to fix. Onsource and recording data again at 21:58 UT. Unlikely to be any useable data between 20:35 - 21:58 UT.

Windstowed at 0413-0433

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbaaug2013/v255tcdlog?rev=1376541552>

Last update: **2015/12/18 16:38**

