

Agilent : 11.1 GHz

SML01 and SML02 both set to 602 MHz

DAS Profile : VSOP.PRO

BG3 cable out

Data recorded to CURTV006B

Observer : Simon

Comments : DAS samplers running hot due to failed fans. System seems to be working OK though.

From:

<https://www.atnf.csiro.au/people/Tasso.Tzioumis/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/Tasso.Tzioumis/vlbi/dokuwiki/doku.php/lbaops/lbaaug2013/v492acdlog>

Last update: **2015/12/18 16:38**

