

Hobart receiver was ~4-5 mm out away from optimal position from start of experiment through to 23:40 UT. Should only have a minor impact on antenna performance.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbaaug2017/v329gholog>

Last update: **2017/08/11 10:09**

