

Recorded data to CURT V006B

Using Agilent @ 13.04 for effective first LO if 8940 MHz.

DAS profile VSOP.PRO

2nd LO 637 for sky freq 8425, 669 for 8457

Coherence in all bandpasses

Pol confirmed with fringe tests on 1921-293.

Bigbuf errors on cDisko between 022157 and 022228

Missing PPS (5/100) lead to restart of recorder @ 0551

Windstowed @0548-0555 0724-0732 0737-0744

Ceduna maser suffered a glitch at ~0100/58, causing a change in the tick phase derivative.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbafeb2009/v252lcdlog>



Last update: **2015/12/18 16:38**