

Recording LCP only (confirmed via Fringe check)

Effective first LO is 2801 MHZ (Agilent 6901 - 4100 fixed)

2nd LOs are 636 for 2285 & 668 for 2317 MHZ

Recording data to ATNF V016A

Recorder encounter bigbuf error between 045930 and 045950. Recorder restarted. Another bigbuf error between 072738-072807

Weather sensor not working throughout experiment.

Drive pc errors and reboot between 0955-1015, trying to fix weather logging problem.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbafeb2009/v293acdlog?rev=1235906139>

Last update: **2015/12/18 16:38**

