

Initially DBBC mode was incorrect, reading RCP output and splitting it into both channels (i.e. LCP and RCP are identical). This has been rectified at 22:18 UT. Recording issues / glitches after about 00:30 UT, in particular unable to fringe check at the end of the run as only one file was transferred.

From:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/doku.php/lbaops/lbafeb2020/v560eholog> 

Last update: **2020/02/21 15:02**