

Agilent 14GHz

SML01&02 777MHz

DAS profile 64MHZ\_N.PRO

Recorded on ATNF V009A, the name of the recording is wrong: v465aho

Started late due to confusion in schedule names

Repeated error "Tsys value for device id overflowed or was less than zero"

No Tsys measurements due to configuration error.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajan2015/v456aholog>

Last update: **2015/12/18 16:38**

