

1805 UT: ASKAP stack had stopped counting down. Restarted system a couple of times. Got it working again around 1818UT.

2228 UT: When ATCA got back up and running, ASKAP seemed to be looking at the wrong source (1308). Restarted the drives.

2350 UT: ASKAP had dropped out again (stack stopped counting down). Restarted.

ASKAP offset at start of experiment by ~100usec from ATCA

From:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/doku.php/lbaops/lbajan2016/v486haklog> 

Last update: **2016/01/22 11:13**