

Agilent 4.1

sky 1720

smy 532

coherence sml=341.8 5th harmonic of 1709

DAS profile VSOP_HO

L-band Rx is cooling

trombone is 53 steps out from IN limit

RX attenuator is 7 dB

need to check Rx attenuator once receiver is fully cool.

Rx chan 2 FET3 LNA current was zero yesterday. fixed by thermal cycling to clr frost

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2009/v289eholog>

Last update: **2015/12/18 16:38**

