

fringe check and main recorded to ATNF V005B

RCP only

first LO 1304 MHz second LO's 428, 684 MHz

DAS profile VSOPXOYO.PRO

UT 09:57 doy 206 The cdisco recording window on ceduna seems to have UT time that is ahead of the TAC by 10 seconds. There is no problem with the fs time. recording is going fine, so I will leave it as is. jd

Network problem to Ceduna 19h UT until 22h UT. FS and recorder still running okay when we connected again. jd

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2010/v271fcdlog>



Last update: **2015/12/18 16:38**