

Recording to pkvsi2, ATNF v014A

Receiver translator jammed in Y1, might be a marginal drop in sensitivity at some elevations due to lack of Rx tracking.

Recording on pkvsi crashed around 13:10 UT, had to restart recorder server and kill a hanging vsib_rcv to allow restart.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2011/v443apalog>

Last update: **2015/12/18 16:38**

